

Location

Lease Road:

Type Main

comment:

Corrective ActionL

Date:

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 452942 Type: WELL API Number: 123-45838 Status: XX Insp. Status: IO

BradenHead

Comment: OK BRADENHEAD PLUMBED TO SURFACE, START 15 PSI, 5 MIN 0 PSI, 10 MIN 0 PSI, 15 MIN 0 PSI, 20 MIN 0 PSI, 25 MIN 0 PSI, 30 MIN 0 PSI PASSED
BRADENHEAD HAD 15 PSI OPENED BRADENHEAD VALVE PRESSURE BLED OF IN 3 SECONDS AND REMAINED AT 0 THROUGHT THE WHOLE TEST

Corrective Action: Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
677400155	WELLHEAD AND TANK BATTERY	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4318212