

Inspection Photos
Location Name: Bunn M 1-34 API: 05-123-11299
Inspection Date: 12/5/2017



Photo 1 – Tank Battery Facility Sign



Photo #2 – AST and buried concrete vessel

Inspection Photos

Location Name: Bunn M 1-34 API: 05-123-11299

Inspection Date: 12/5/2017



Photo 3 – Pothole at separator at former location of the abandoned McIntyre 34-16 flowline riser.



Photo 4 – Separator at Bunn M 1-34 production facility.

