

**Boomerang 1-21 Pad Baseline Water Source Research**

<b>Potential Sample Locations</b>	
<b>DWR Receipt #</b>	<b>Notes</b>
9058510	Owned by Jim Gerwig. Contacted Mr. Gerwig via phone on 9/27/17. Per Mr Gerwig: no pump is in well, well is filled with rocks and is inoperable.
452932	Owned by Ronnie Jackson. Contacted Mr. Jackson 11/2/17. Mr. Jackson said well is slow producing but operable. Attempted sample collection at the well location on 11/7/17. Well produces about 1 gallon per hour and is piped directly into a cistern that is filled with water hauled in from offsite. Not possible to collect representative sample from the well.
403847 and 360372	DWR records wells are located in a new subdivision constructed around 2015. Inspected location via field visit on 11/09/2017, and wells could not be located. No response received from homeowners association. Suspected to be destroyed during construction activities.
9061893 and 9060229	Owned by NCMC Banner Health. Contacted Mr. Ken Shultz on 11/8/17. SRC received correspondence from NCMC Banner Health denying access to sample.
9065001	Owned by Excel Energy. Access denied via phone call with Mr. Quinn Kilty (Excel Energy Environmental Representative) on 10/24/17.
3668320U	Geothermal well, inapplicable.
0330433B and 0330433A	Applications unacceptable.
90162	No well installed, dry hole per DWR records.
3611403A	Monitoring well, inapplicable.
3611403B	Monitoring well, inapplicable.
3611403C	Monitoring well, inapplicable.
3611403D	Monitoring well, inapplicable.
3611403E	Monitoring well, inapplicable.
3611403F	Monitoring well, inapplicable.
3611403G	Monitoring well, inapplicable.
25972	Monitoring well, inapplicable.
28758	Monitoring well, inapplicable.
46201	Monitoring well, inapplicable.