

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/05/2017

Submitted Date:

12/05/2017

Document Number:

679903521

FIELD INSPECTION FORM

Loc ID 305043 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69760
Name of Operator: PETRON DEVELOPMENT COMPANY
Address: 1899 W LITTLETON BLVD
City: LITTLETON State: CO Zip: 80120

Findings:

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|----------------|----------------|---------|
| Walker, Jimmy | (303) 794-5300 | jim@petron.net | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 277686 | WELL | PR | 06/12/2005 | GW | 125-09289 | ZUEGE*ALLEN 1-8 | PR |

General Comment:

Routine Inspection

Location

| | | | |
|--------------------|---------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Trail through farm ground | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------------|---|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign mounted to fence at unit | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Lease signs at pit on south side of CR 23 | | |
| Corrective Action: | | Date: | |

| | | | |
|----------------------------------|--|-------|--|
| Emergency Contact Number: | | | |
| Comment: | <input style="width: 95%;" type="text"/> | | |
| Corrective Action: | <input style="width: 95%;" type="text"/> | Date: | <input style="width: 80%;" type="text"/> |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|---------------------------------------|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Metal panels around unit and wellhead | | |
| Corrective Action: | | Date: | |
| Type | PIT | | |
| Comment: | Metal panels around pit | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|----------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Pump Jack | # 1 | | |
| Comment: | Jensen unit | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric motor | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Electric panel | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 277686 Type: WELL API Number: 125-09289 Status: PR Insp. Status: PR

Producing Well

Comment: Producing. Casing production. Central meter run for (Miller 4-32, 33-32, 43-32, ZUEGE 1-8, 2-8, 3-8) 1.25 miles N @ Mountain Miller 4-32. Production pit for (Zuege 1-8, 2-8 & 3-8) 500' N on S side of CR 23

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other | Pass | Compaction | Pass | | | |

Comment: [Location is farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT