

Inspection Photos
Well Name: Nigh 19-3
Location ID: 312637



Photo 1. No surface evidence of well.



Photo 2. Debris on location.

Inspection Photos
Well Name: Nigh 19-3
Location ID: 312637



Photo 3. Debris on location.



Photo 4. Production equipment still on location.

Inspection Photos
Well Name: Nigh 19-3
Location ID: 312637



Photo 5. Tank still on location.