

Inspection Photos

12/04/2017

Operator: MURFIN DRILLING COMPANY INC -
61650

Location ID: 453292

Inspection Doc. Number: 682502904
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: MURFIN DRILLING COMPANY INC - 61650
Location ID: 453292



Photo 1: Photo taken from the southwest corner of the location, facing north. Photo shows surface roughening along the perimeter of the location. Photo also shows a pre-existing ditch on the west end of the location that operator has incorporated into the SW BMPS.



Photo 2: Photo taken from the southwest corner of the location, facing east. Photo shows surface roughening along the perimeter of the location

Inspection Photos
Operator: MURFIN DRILLING COMPANY INC - 61650
Location ID: 453292



Photo 3: Photo taken from the northwest corner of the location, facing south. Photo shows surface roughening along the perimeter of the location



Photo 4: Photo taken from the northwest corner of the location, facing east. Photo shows surface roughening along the perimeter of the location

Inspection Photos
Operator: MURFIN DRILLING COMPANY INC - 61650
Location ID: 453292



Photo 5: Photo taken from the northeast corner of the location, facing west. Photo shows surface roughening along the perimeter of the location



Photo 6: Photo taken from the northeast corner of the location, facing south. Photo shows surface roughening along the perimeter of the location

Inspection Photos
Operator: MURFIN DRILLING COMPANY INC - 61650
Location ID: 453292



Photo 7: Photo taken from the southeast corner of the location, facing north. Photo shows surface roughening along the perimeter of the location



Photo 8: Photo taken from the southeast corner of the location, facing west. Photo shows surface roughening along the perimeter of the location