

# Inspection Photos

12/04/2017

Operator: PCR OPERATING LLC - 10657

Location ID: 313755

Inspection Doc. Number: 682502913


Morgan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: PCR OPERATING LLC - 10657  
Location ID: 313755



**Photo 1:** Photo taken from the well location, facing east. Photo shows pump unit has been removed per corrective actions. Previous inspections also required operator to perform revegetation activities and ensure seeded soil is stabilized. Unable to find evidence that reseeded or additional reclamation activities have been conducted.



**Photo 2:** Photo taken at the well location. Photo shows soil surface; unable to find evidence that reseeded or additional reclamation activities have been conducted.



**Photo 3:** Photo taken from the well location facing south. Previous inspection required operator to perform reclamation on the access road. Photo shows no reclamation activities have been conducted on access road.