



**Photo 1. View of the project area from the northeastern corner facing center.**



**Photo 2. View from the northern corner of the project area from the northeastern corner facing westward. Per COGCC documentation, former pit area is being remediated. Flagging appears to indicate this area.**



**Photo 3. View of the western portion of the project area from the southwestern corner facing northward.**