

Inspection Photos
Location Name: Hume 1
API: 05-009-06118



1. Inadequate lease sign



2. Other half of Inadequate lease sign

Inspection Photos
Location Name: Hume 1
API: 05-009-06118



3. Unit without a prime mover



4. Access covered with weeds



Inspection Photos
Location Name: Hume 1
API: 05-009-06118



5. Unused equipment



6. Meter shed

Inspection Photos
Location Name: Hume 1
API: 05-009-06118



7. Water tank with no berms or labeling



8. Inadequate wildlife screening