

# Final Reclamation Inspection

December 4, 2017

Operator: K P KAUFFMAN COMPANY INC- #46290

Location ID: 319000

Weld County, CO

SESE Section 4 T1N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: CHAMPLIN 86 AMOCO F #3  
Location ID: 319000



**Photo 1.** Photo taken from where equipment has been left at the location, facing East. Operator has failed to remove equipment per the previous corrective action inspection and is currently over 5 years out of compliance with Reclamation rules.