

Final Reclamation Inspection

December 4, 2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

API: 05-123-08646

Weld County, CO

SWNE Section 4 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: CHAMPLIN 32-4 #2

API: 05-123-08646



Photo 1. Photo taken from the well location, facing Northwest. Subsidence might be present at the well location. Location will be inspected at a future date to assess vegetative conditions during an active crop growing season to ensure an accurate assessment is conducted.



Photo 2. Photo taken from the well location, facing North. See comments under Photo 1.