

Final Reclamation Inspection

December 4, 2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

API: 05-123-22438

Weld County, CO

SWSE Section 4 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SEC. 4 INVESTORS #34-4
API: 05-123-22438



Photo 1. Photo taken from the well location, facing South. Subsidence might be present at the well location. Location will be inspected at a future date to assess vegetative conditions during an active crop growing season to ensure an accurate assessment is conducted.



Photo 2. Photo taken from the well location, facing West. See comments under Photo 1.