

GUNNISON ENERGY LLC – 10515

API # 05-029-06109 SPU COCKROFT 1294 23-41D-H

API # 05-029-06112 SPU COCKROFT 1294 23-41D H1R

Inspection Date : 12/7/2017



Location entrance looking W.



SI well with pump jack (05-029-06112)  
and TA well (05-029-06109)

GUNNISON ENERGY LLC – 10515

API # 05-029-06109 SPU COCKROFT 1294 23-41D-H

API # 05-029-06112 SPU COCKROFT 1294 23-41D H1R

Inspection Date : 12/7/2017



**NGL tank scheduled for removal**



**Tank battery and ECDs disconnected for removal**



GUNNISON ENERGY LLC – 10515

API # 05-029-06109 SPU COCKROFT 1294 23-41D-H

API # 05-029-06112 SPU COCKROFT 1294 23-41D H1R

Inspection Date : 12/7/2017



**Separator and misc equipment in  
process of removal**



**Site of previous separator and risers removed.**