

Inspection Photos

12/07/2017

Operator: DJ RESOURCES INC - 10213

Location ID: 390645

Inspection Doc. Number: 682502921

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: DJ RESOURCES INC - 10213
Location ID: 390645



Photo 1: Photo taken from the north end of the location, facing southeast. Photo shows location appears to have been reseeded and then crimped with straw for stabilization.



Photo 2: Photo taken from the north end of the location, facing south. Photo shows location appears to have been reseeded and then crimped with straw for stabilization.