

# Inspection Photos

12/07/2017

Operator: DJ RESOURCES INC - 10213

Location ID: 390646

Inspection Doc. Number: 682502923

Logan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: DJ RESOURCES INC - 10213  
Location ID: 390646



**Photo 1:** Photo taken from the north end of the location, facing southeast. Photo shows location appears to have been reseeded and then crimped with straw for stabilization.



**Photo 2:** Photo taken from the north end of the location, facing south. Photo shows location appears to have been reseeded and then crimped with straw for stabilization.