

Inspection Photos

12/07/2017

Operator: WESTERN OPERATING COMPANY -
95620

Location ID: 312292

Inspection Doc. Number: 682502925

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 1: Photo taken from the location, facing northeast. Photo shows areas of erosion degradation. Erosion has not been repaired or stabilized and no BMPs have been installed or maintained per corrective actions.



Photo 2: Photo taken from the east end of the produced water pit. See comments under photo 1.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 3: Photo taken from the south end of the location, facing south. See comments under photo 1.



Photo 4: Photo taken from the south of the location (to the east of the produced water pit). See comments under photo 1

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 5: Photo taken from the south of the location (to the east of the produced water pit). See comments under photo 1



Photo 6: Photo taken from the southeast end of the produced water pit, facing south. Photo shows areas of erosion degradation on the adjacent lands due to runoff and salt kill. Photo shows no remediation activities appear to have been conducted, and no stabilization and stormwater BMPs have been installed or maintained per the corrective actions.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 7: Photo taken from the southwest end of the produced water pit, facing north. See comments under photo 6




Photo 8: Photo taken from the southwest end of the produced water pit, facing west. See comments under photo 6.