

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/24/2017

Submitted Date:

12/08/2017

Document Number:

680102457**FIELD INSPECTION FORM**

Loc ID 335622	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 5 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																															
<b>Operator Information:</b> OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>																																																																			
<b>Contact Information:</b> <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td></td> <td></td> <td>cogcc.inspections@caerusoila ndgas.com</td> <td>Piceance inspections only</td> </tr> </table>					Contact Name	Phone	Email	Comment			cogcc.inspections@caerusoila ndgas.com	Piceance inspections only																																																							
Contact Name	Phone	Email	Comment																																																																
		cogcc.inspections@caerusoila ndgas.com	Piceance inspections only																																																																
<b>Inspected Facilities:</b> <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr> <td>278533</td> <td>WELL</td> <td>PR</td> <td>06/24/2005</td> <td>GW</td> <td>045-10887</td> <td>N. PARACHUTE WF03D N23 596</td> <td>PR</td> </tr> <tr> <td>278744</td> <td>WELL</td> <td>PR</td> <td>07/12/2005</td> <td>GW</td> <td>045-10926</td> <td>N. PARACHUTE WF13B N23 596</td> <td>PR</td> </tr> <tr> <td>278745</td> <td>WELL</td> <td>PR</td> <td>04/18/2007</td> <td>GW</td> <td>045-10925</td> <td>N. PARACHUTE WF06B N23 596</td> <td>PR</td> </tr> <tr> <td>279486</td> <td>WELL</td> <td>PR</td> <td>05/04/2007</td> <td>GW</td> <td>045-11049</td> <td>N. PARACHUTE WF04D N23 596</td> <td>PR</td> </tr> <tr> <td>279487</td> <td>WELL</td> <td>SI</td> <td>07/01/2017</td> <td>GW</td> <td>045-11048</td> <td>N. PARACHUTE WF03B N23 596</td> <td>SI</td> </tr> <tr> <td>279494</td> <td>WELL</td> <td>PR</td> <td>04/12/2007</td> <td>GW</td> <td>045-11052</td> <td>N. PARACHUTE WF16D N23 596</td> <td>PR</td> </tr> <tr> <td>279496</td> <td>WELL</td> <td>PR</td> <td>08/22/2005</td> <td>GW</td> <td>045-11050</td> <td>N. PARACHUTE WF04B N23 596</td> <td>PR</td> </tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	278533	WELL	PR	06/24/2005	GW	045-10887	N. PARACHUTE WF03D N23 596	PR	278744	WELL	PR	07/12/2005	GW	045-10926	N. PARACHUTE WF13B N23 596	PR	278745	WELL	PR	04/18/2007	GW	045-10925	N. PARACHUTE WF06B N23 596	PR	279486	WELL	PR	05/04/2007	GW	045-11049	N. PARACHUTE WF04D N23 596	PR	279487	WELL	SI	07/01/2017	GW	045-11048	N. PARACHUTE WF03B N23 596	SI	279494	WELL	PR	04/12/2007	GW	045-11052	N. PARACHUTE WF16D N23 596	PR	279496	WELL	PR	08/22/2005	GW	045-11050	N. PARACHUTE WF04B N23 596	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																												
278533	WELL	PR	06/24/2005	GW	045-10887	N. PARACHUTE WF03D N23 596	PR																																																												
278744	WELL	PR	07/12/2005	GW	045-10926	N. PARACHUTE WF13B N23 596	PR																																																												
278745	WELL	PR	04/18/2007	GW	045-10925	N. PARACHUTE WF06B N23 596	PR																																																												
279486	WELL	PR	05/04/2007	GW	045-11049	N. PARACHUTE WF04D N23 596	PR																																																												
279487	WELL	SI	07/01/2017	GW	045-11048	N. PARACHUTE WF03B N23 596	SI																																																												
279494	WELL	PR	04/12/2007	GW	045-11052	N. PARACHUTE WF16D N23 596	PR																																																												
279496	WELL	PR	08/22/2005	GW	045-11050	N. PARACHUTE WF04B N23 596	PR																																																												

Contact Name	Phone	Email	Comment
		cogcc.inspections@caerusoila ndgas.com	Piceance inspections only

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278533	WELL	PR	06/24/2005	GW	045-10887	N. PARACHUTE WF03D N23 596	PR
278744	WELL	PR	07/12/2005	GW	045-10926	N. PARACHUTE WF13B N23 596	PR
278745	WELL	PR	04/18/2007	GW	045-10925	N. PARACHUTE WF06B N23 596	PR
279486	WELL	PR	05/04/2007	GW	045-11049	N. PARACHUTE WF04D N23 596	PR
279487	WELL	SI	07/01/2017	GW	045-11048	N. PARACHUTE WF03B N23 596	SI
279494	WELL	PR	04/12/2007	GW	045-11052	N. PARACHUTE WF16D N23 596	PR
279496	WELL	PR	08/22/2005	GW	045-11050	N. PARACHUTE WF04B N23 596	PR

**General Comment:**

This is an Interim Reclamation & Stormwater focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

Inspected Facilities				
Facility ID: <u>278533</u>	Type: <u>WELL</u>	API Number: <u>045-10887</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>278744</u>	Type: <u>WELL</u>	API Number: <u>045-10926</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>278745</u>	Type: <u>WELL</u>	API Number: <u>045-10925</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>279486</u>	Type: <u>WELL</u>	API Number: <u>045-11049</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>279487</u>	Type: <u>WELL</u>	API Number: <u>045-11048</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>279494</u>	Type: <u>WELL</u>	API Number: <u>045-11052</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>279496</u>	Type: <u>WELL</u>	API Number: <u>045-11050</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? PassProduction areas stabilized ? Pass1003c. Compacted areas have been cross ripped? Pass1003d. Drilling pit closed? PassSubsidence over on drill pit? Pass

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? InProduction areas have been stabilized? Pass

Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured Pass80% Revegetation Pass

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? P

Comment

Areas no Longer in use have been reclaimed. Site is well contoured and has Good Vegetation. Only Concern at this Site is addressed in Stormwater Section. Refer to Photos attached.

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_Contoured \_\_\_\_\_Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Berms	Pass					
Compaction	Fail					Pad eroding; Refer below
Ditches	Pass					
Sediment Traps	Pass					
Retention Ponds	Pass					
Seeding	In Process					

Comment: [Chanel erosion of Pad is occurring at South end of Pad. Material/ Sediment is migrating into Sediment Retention area. Refer to Photos attached.](#)

Corrective Action: [CA: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.](#)

Date: 01/08/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680102458	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4321167">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4321167</a>