


Photo Log - Sack 2C-30HZ – Inspection 07/14/2017



Well Sign



Horizontal Separator, a pop off valve on which was the release point for the plume observed by the complainant.

