

Photo#1:
Overview of Location from top of South Cut Slope to North



December 7, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Creek Loc#452807

Photo#2:

View from top of East Fill Slope down over East Sediment Trap at base of Slope. Sediment traps installed at base of East & West sides of Fill Slopes do not appear to have been installed with good engineering practices.



December 7, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Creek Loc#452807

Photo#3:

View from bottom of West Fill Slope over West Sediment Trap up Fill Slope to East. Sediment traps installed at base of East & West side of Fill Slopes do not appear to have been installed with good engineering practices.



December 7, 2017

Photo#4:

Photo#5:

BMPs installed along each side of Access Road .



December 7, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Creek Loc#452807

Photo#6:

Silt Fence Installed along Access Road & Perimeter of Location.

Photo#7:



December 7, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Creek Loc#452807

Photo#8:

Photo#9:

Views along Top soil piled at top of South Cut Slope.



December 7, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Creek Loc#452807