

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/11/2017

Submitted Date:

12/11/2017

Document Number:

674200348

**FIELD INSPECTION FORM**

Loc ID 452217 Inspector Name: Gomez, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
, Inspections		COGCCinspections@Anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452260	WELL	XX	09/21/2017		123-45494	YELLOWHAMMER 4C-8HZ	DG
452263	WELL	XX	09/21/2017		123-45497	YELLOWHAMMER 30N2-8HZ	DG
452266	WELL	XX	09/21/2017		123-45500	YELLOWHAMMER 30N-8HZ	DG

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	APPROX 32' SOUND WALLS SURROUND LOCATION FOR SOUND AND LIGHTING MITIGATION		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	Field Flare		
Comment:	NOT IN USE AT TIME OF INSPECTION		
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 452260 Type: WELL API Number: 123-45494 Status: XX Insp. Status: DG

Facility ID: 452263 Type: WELL API Number: 123-45497 Status: XX Insp. Status: DG

**Complaint**

Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 452266 Type: WELL API Number: 123-45500 Status: XX Insp. Status: DG

**Complaint**

Comment: Well Number#: Location #: 452217  
Inspection Document #: 674200348  
Complaint #s: 200444754-200444753  
  
Nature of complaint: Odors/Noise  
  
Field Inspector Actions:  
  
On 12-11-2017, I was contacted by complaint specialist Megan Adamczyk in reference to several complaints received for 12-9-2017 and 12-10-2017 by the COGCC about odors occurring in the Erie area south of the Anadarko, Papa Jo location.  
  
On 12-11-2017 at approx 1100 hrs I performed a complete site inspection of the Papa Jo location and the neighborhoods around the location. At the time of inspection, I observed the drilling rig performing normal drilling operation on location. I contacted Travis Kruckenberg from Anadarko who indicated the rig had been performing normal drilling activity at the time of the complaints. Travis indicated the flaring on Friday evening was consistent with normal drilling operations. At the time of the inspection of the drilling rig Travis also indicated Anadarko was also using an odor neutralizer to mitigate odors at the drilling rig. At the time of the inspection all lighting on location appeared to be pointed toward the ground and center of location. I reviewed location records, which did not show any abnormal drilling operations at the time of the complaints.  
As part of the inspection prior to the rig inspection I checked the area of the complaints residence for odors and at the time of the inspection I did not detect any odors off location during my investigation.  
All information reviewed and site inspection information were submitted to the COGCC for further review.  
  
No violations of COGCC rules were observed at the time of the inspection  
  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Well Drilling**

**Rig:** Rig Name: XTREME RIG 24 Pusher/Rig Manager: TRAVIS  
 Permit Posted: Yes Access Sign: Yes

**Well Control Equipment:**  
 Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: \_\_\_\_\_ Safety Plan: YES

**Drill Fluids Management:**  
 Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: YES Disposal Location: WASTE MANAGEMENT  
 Comment: \_\_\_\_\_

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass			Vehicle Tracking	Pass	
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Culverts	Pass					
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT