



Photo 1. View of area along the access road where silt trap was recently cleaned and sediment placed offsite into adjacent sagebrush habitat.



Photo 2. View of area along access road where sediment from roadside ditch was placed into adjacent sagebrush habitat.



Photo 3. View of another area along the access road where silt trap was maintained and sediment placed in adjacent habitat.



Photo 4. View of area along the access road where sediment and soil has been scraped and placed in piles along roadside and in adjacent grass/sagebrush habitats.

