

Inspection Photos  
Location Name: HSR-Leberman 16-1 63N67W #1SESE  
API: 05-123-16383



Photo 1 Wellhead API – 05-123-16383 from west



Photo 2 Tank Battery from west

## Inspection Photos

Location Name: HSR-Leberman 16-1 63N67W #1SESE

API: 05-123-16383



Production equipment from southwest

