

Inspection Photos
Location Name: Schank J 35-08
API #: 05-123-19203
Location ID: 330495



Wellhead looking north



Battery looking east

Inspection Photos
Location Name: Schank J 35-08
API #: 05-123-19203
Location ID: 330495



Unused/disconnected gas meter run needs to be removed