

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2017

Submitted Date:

12/12/2017

Document Number:

679903558

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 311098 _____ Welsh, Brian _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 55575
 Name of Operator: MCELVAIN ENERGY INC
 Address: 1050 17TH ST STE 2500
 City: DENVER State: CO Zip: 80265-

Findings:

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|------------------------|--------------------------|---------|
| Cooper, Tony | (303) 893-0933 x331 | tony.cooper@mcelvain.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 298825 | WELL | PR | 03/15/2010 | GW | 125-11491 | MASSIVE 19-7 | PR |

General Comment:

[Routine Inspection](#)

Location

| | | | |
|--------------------|---------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Dirt road through pasture | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------------|--------------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by metal shed | | |
| Corrective Action: | | Date: | |

| | | | |
|----------------------------------|--|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Metal panels around wellhead, metal shed and VGS | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Meter run in metal shed | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 2 | | |
| Comment: | 1-Vertical gas separator 50% buried by metal shed 1-Vertical gas separator in metal shed | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Telemetry equipment | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------|--|--|--|
| Flaring: | | | |
| Type | | | |

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 298825 Type: WELL API Number: 125-11491 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT