

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2017

Submitted Date:

12/12/2017

Document Number:

679903562

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Welsh, Brian On-Site Inspection
 311096 _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 55575
 Name of Operator: MCELVAIN ENERGY INC
 Address: 1050 17TH ST STE 2500
 City: DENVER State: CO Zip: 80265-

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Cooper, Tony	(303) 893-0933 x331	tony.cooper@mcelvain.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298816	WELL	PR	03/15/2010	GW	125-11489	MASSIVE 19-10	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Dirt road through pasture		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by metal shed		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No
 Comment: _____
 Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Metal panels around wellhead, chemical tank, metal shed, VGS and pig station		
Corrective Action:			Date:

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Telemetry equipment and chemical tank w/containment		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Meter run in metal shed		
Corrective Action:			Date:
Type: Vertical Separator	# 2		
Comment:	1-Vertical gas separator 50% buried by metal shed 1-Vertical gas separator in metal shed		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:	Pig station on west side of location		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 298816 Type: WELL API Number: 125-11489 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT