

Inspection Photos
Location Name: Loustalet #41-15
API: 05-123-19236



Photo 1: Location, looking W



Photo 2: Wellhead, looking N



Inspection Photos
Location Name: Loustalet #41-15
API: 05-123-19236



Photo 3: Unlabeled container



Photo 4: Stormwater erosion on road leading to separator, looking SW

Inspection Photos
Location Name: Loustalet #41-15
API: 05-123-19236



Photo 5: Stormwater erosion on W side of battery, looking S



Photo 6: Trash and debris on location