

Photo#1:
Overview of Location from Entry to North.



December 7, 2017

Photo#2:

View from South to North over Well lineup & Gravel filled Cellars.



December 7, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Marathon ALS on Loc#335985

Photo#3:

View from North South over Well lineup & Gravel filled Cellars.



December 7, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Marathon ALS on Loc#335985

Photo#4:

Risers / Stubbs located at back (East side) of each Cellar.



December 7, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Marathon ALS on Loc#335985