

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 1: Wellhead sign. Previous inspection.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 2: Wellhead sign.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 3: Sediment plume from stormwater run on behind production equipment.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 4: Cleaned up area.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 5: Erosion channel carrying stormwater and sediment into production area.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 6: Repaired erosion channel.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 7: Erosion channel off SE corner of location.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 8: Repaired erosion channel.