

# Final Reclamation Inspection

December 12, 2017

Operator: MAGPIE OPERATING, INC- # 52530

API: 05-069-06112

Larimer County, CO

SESE Section 29 T5N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: SAULCY #3  
API: 05-069-06112



Google Earth aerial imagery taken June 19, 2014 illustrating an approximate 770' access road AND well location that has not been reclaimed per Rule 1004 standards.

Inspection Photos  
Location Name: SAULCY #3  
API: 05-069-06112



**Photo 1.** Photo taken on May 26, 2017 from the access point off CO Rd. 16, facing North along the access road. Gravel has not been removed and access road has not been contoured.



**Photo 2.** Photo taken on May 26, 2017 north of the previous photo location, facing North along the access road. See comments under Photo 1.



Inspection Photos  
Location Name: SAULCY #3  
API: 05-069-06112



**Photo 3.** Photo taken on May 26, 2017 north of the previous photo location, facing North along the access road. See comments under Photo 1.



**Photo 4.** Photo taken on May 26, 2017 north of the previous photo location, facing North along the access road. See comments under Photo 1.

Inspection Photos  
Location Name: SAULCY #3  
API: 05-069-06112



**Photo 5.** Photo taken on May 26, 2017 from the well location, facing North. Gravel has not been removed and has not been contoured.



**Photo 6.** Photo taken on December 12, 2017 from the access point off CO Rd. 16, facing North. Land has been recently tilled. It appears the access road may not have been recontoured as soil material appeared to be elevated along the access road in relation to the adjacent land.