

# Inspection Photos

12/11/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 408094

Inspection Doc. Number: 682502933

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the former battery facility. Previous inspections required operator to remove abandoned gathering riser in accordance to COGCC reclamation rule 1004.a. Photo shows riser has not been removed.