

# Inspection Photos

12/11/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 323427

Inspection Doc. Number: 682502937

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 323427



**Photo 1:** Photo taken from the northeast end of the former tank battery facility, facing west. Photo shows additional reclamation activities have been conducted at the battery.



**Photo 2:** Photo taken from the northeast end of the former tank battery facility, facing southwest. Photo shows additional reclamation activities have been conducted at the battery.






**Photo 3:** Photo taken from the northeast end of the former tank battery facility, facing south. Photo shows access road leading to the well location has not been reclaimed.



Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 323427



**Photo 4:** 1984 USGA aerial imagery. Well was SPUD 1986. Photo shows location prior to oil and gas activities. Photo shows access road and battery location did not pre-exist oil and gas activities.



**Photo 5:** 2012 Aerial imagery. Photo shows the **well** and **battery** location, as well as the **access road**