

Photo#1:

View of Location from Southwest to Northeast .



December 5, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa PA Porter API#045-19727

Photo#2:
View along Cut Slope, North to South.



December 5, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa PA Porter API#045-19727

Photo#3:

Sediment trap at base of Fill Slope, West of Entry appears to need some adjustment. Slopes appear to be steeper than 2:1. Outlet?



December 5, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa PA Porter API#045-19727

Photo#4:

Blankets on Slopes appear to need Maintenance.

Photo#5:



December 5, 2017