

Inspection Photos

12/12/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 453292

Inspection Doc. Number: 682502952

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 453292



Photo 1: Photo taken from the north end of the tank battery location, facing south. Photo shows the majority of the location appears to have had additional reclamation work conducted, however, photo also shows meter shed equipment has not been removed per the corrective action.



Photo 2: Photo taken from the north end of the tank battery location, facing southwest. Photo shows the majority of the location appears to have had additional reclamation work conducted, however, photo also shows meter shed equipment has not been removed per the corrective action.



Photo 3: Photo taken from the tank battery location, facing southwest. Photo shows meter shed equipment and “Noble Energy” sign has not been removed per the corrective action.