

Inspection Photos

12/12/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 323052

Inspection Doc. Number: 682502962

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323052



Photo 1: Photo taken from the east end of the well location, facing southwest. Photo shows additional reclamation activities at the well and access road appear to have been conducted per the corrective actions.



Photo 2: Photo taken from the east end of the well location, facing northwest. Photo shows additional reclamation activities at the well and access road appear to have been conducted per the corrective actions.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323052



Photo 3: Photo taken from the active tank battery, facing west. Photo shows erosion degradation has been repaired.



Photo 4: Photo taken from the active tank battery, facing northwest. Photo shows erosion degradation has been repaired.