



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is progressing with grasses such as western wheatgrass (*Pascopyrum smithii*) and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3. View of the southern portion of the project area from the southeastern corner facing westward. Project area is surrounded by a grass field.



Photo 4. View of area in the northern portion of the project area that appears to be prepared for reclamation.



Photo 5. View of stormwater controls at the entrance to the well pad.