

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2017

Submitted Date:

12/15/2017

Document Number:

680302824

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: SCHURE, KYM On-Site Inspection
313815 _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 76840
Name of Operator: SCHNEIDER ENERGY SERVICES INC
Address: P O BOX 889
City: FORT MORGAN State: CO Zip: 80701

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Schneider, Jeff	970-867-9437/ (214) 244-3819	jeff@schneiderenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
225492	WELL	PR	04/29/2007	OW	087-05905	REGGIE 1	PR

General Comment:

Routine Site Inspection - SATISFACTORY

Location			
Lease Road:			
Type	Access		
comment:	Access off County Road. Entrance road to battery could use dressing up, fill ruts and grade.		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Satisfactory		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Satisfactory		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Satisfactory		
Corrective Action:		Date:	
Equipment:			
Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	NG Engine		
Corrective Action:		Date:	

Type: Ancillary equipment	# 1		
Comment:	Propane tank @ separator		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.173431,-103.796272
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 225492 Type: WELL API Number: 087-05905 Status: PR Insp. Status: PR

Producing Well

Comment: [Pumping OW](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: [Use BMP's for stormwater erosion management](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT