

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/15/2017

Submitted Date:

12/15/2017

Document Number:

690000942**FIELD INSPECTION FORM**

Loc ID 449884 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449887	WELL	DG	10/24/2017		123-44568	NEWBY 2N-33HZ	DG

General Comment:

Inspected FacilitiesFacility ID: 449887 Type: WELL API Number: 123-44568 Status: DG Insp. Status: DG**Well Drilling**

Rig: Rig Name: Nabors Rig X22 Pusher/Rig Manager: Adam Nissen
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: YES Blind Ram: Hydril Type:
 Pressure Test BOP: Pass Test Pressure PSI: Safety Plan: YES

Drill Fluids**Management:**

Lined Pit: Unlined Pit: Closed Loop: YES Semi-Closed Loop:
 Multi-Well: Disposal Location:
 Comment:
 Corrective Action: Date:

COGCC Comments

Comment	User	Date
Routine inspection. Company representative on location: Carlton, Cooley	carlilec	12/15/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690000943	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4327437