

HRM Resources II LLC, Scheetz 1  
121-08865  
Inspection #688300792  
12/12/2017  
Routine Inspection

**HRM RESOURCES, LLC**  
720-836-6046

LIC.#74770 SCHEETZ 1  
800-373-1005 OR 911  
W/2 SEC 23-3S-52W 121  
COUNTY ROAD EE/15


12.12.2017





12.12.2017





HRM  
LIC.#74  
800-3  
W/2 SEC  
COUN

12.12.2017





12.12.2017



12.12.2017





Label lines

12.12.2017





12.12.2017





12.12.2017





Valve leak, not on ground

12.12.2017









Maintain tank berms

12.12.2017





• Maintain tank berms


12.12.2017





12.12.2017



A photograph of a desert landscape. In the foreground, a large white cylindrical tank is partially visible on the right side. To its left, there is some debris, including a long wooden log and some metal parts. In the background, a white SUV is parked on a dirt road. The sky is clear and blue. The text "Unused equipment" is overlaid on the image.

Unused equipment

12.12.2017



# PRODUCED WATER

**HEALTH HAZARD**  
4 Deadly  
3 Extreme Danger  
2 Hazardous  
1 Slightly Hazardous  
0 Normal Material



**FIRE HAZARD**  
Flash Points  
4 Below 73° F  
3 Below 100° F  
2 Below 200° F  
1 Above 200° F  
0 Will not burn


**SPECIFIC HAZARD**  
Oxidizer OX  
Acid ACID  
Alkal ALK  
Corrosive COR  
Use NO Water W  
Radioactive \*

**REACTIVITY**  
4 May detonate  
3 Shock and heat may detonate  
2 Violent chemical change  
1 Unstable if heated  
0 Stable

300 BBL'S

12.12.2017





Maintain berm at produced  
water tank and pit on SE corner

12.12.2017





12.12.2017





12.12.2017





12.12.2017





Oil on pit

12.12.2017





Oil on pit

12.12.2017