

**Petroglyph Operating Company, Inc. Raton Field:
Road Maintenance and Erosion Control Work Report-December 2017**



Loose Rock Check Dams: Between State 7W and State 9W northeast side of access road



Loose Rock Check Dams: Between State 7W and State 9W northeast side of access road



Loose Rock Check Dams: Between State 9W and State 10WB northeast side of access road



Loose Rock Check Dams: between State 9W and State 10WB northeast side of access road



Water Bar #1 Between State 7 W and State 9 W near crest of hill
