Interim Reclamation and Stormwater Inspection

December 15, 2017

Operator: PDC ENERGY INC - #69175

Location ID: 450111

Weld County, CO

SWNE Section 24 T5N R65W

Chris Binschus
Reclamation Specialist, COGCC

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

Inspection Photos
Location Name: Sandin /5N65W24N
Location ID: 450111

Photo 1. Photo taken from the entrance of location, facing West. Vehicle tracking devices installed.

Photo 2. Photo taken from the entrance of location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: Sandin /5N65W24N
Location ID: 450111

Photo 3. Photo taken from the northeastern location, facing South. Sediment trap has been installed with a stabilized outlet protection device.

Photo 4. Photo taken from the northeastern location, facing South. Ditch and berm BMP installed around the perimeter of the location.

Photo 5. Photo taken from the southeastern location, facing West. See comments under Photo 4. Appears topsoil has been salvaged and stored along the southern perimeter. Topsoil has been temporarily stabilized by equipment tracking.

Photo 6. Photo taken from the western location, facing West. A retention area has been constructed with no outlet protection device.

Photo 7. Photo taken from the western location, facing West. See comments under Photo 4.

Photo 8. Photo taken from the western location, facing North. See comments under Photo 4.

Inspection Photos
Location Name: Sandin /5N65W24N
Location ID: 450111

Photo 9. Photo taken from the western location, facing East. See comments under Photo 4.

Photo 10. Photo taken from the northeastern location, facing East. See comments under Photo 3.