

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/07/2017

Submitted Date:

12/12/2017

Document Number:

680102476**FIELD INSPECTION FORM**

Loc ID 335985	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 2 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																															
Operator Information: OGCC Operator Number: <u>53650</u> Name of Operator: <u>MARATHON OIL COMPANY</u> Address: <u>1501 STAMPEDE AVENUE</u> City: <u>CODY</u> State: <u>WY</u> Zip: <u>82414</u>																																																																			
Contact Information: <table border="1"> <thead> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td>Newton, Phil</td> <td>713-296-3508</td> <td>penewton@marathonoil.com</td> <td></td> </tr> <tr> <td></td> <td></td> <td>cogcc.inspections@caerusoila ndgas.com</td> <td></td> </tr> </tbody> </table>					Contact Name	Phone	Email	Comment	Newton, Phil	713-296-3508	penewton@marathonoil.com				cogcc.inspections@caerusoila ndgas.com																																																				
Contact Name	Phone	Email	Comment																																																																
Newton, Phil	713-296-3508	penewton@marathonoil.com																																																																	
		cogcc.inspections@caerusoila ndgas.com																																																																	
Inspected Facilities: <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>296400</td><td>WELL</td><td>AL</td><td>03/31/2016</td><td>LO</td><td>045-15997</td><td>697-2C 18</td><td>RI</td></tr> <tr><td>296401</td><td>WELL</td><td>AL</td><td>03/31/2016</td><td>LO</td><td>045-15998</td><td>697-2C 14</td><td>RI</td></tr> <tr><td>296402</td><td>WELL</td><td>AL</td><td>03/31/2016</td><td>LO</td><td>045-15999</td><td>697-2C 12</td><td>RI</td></tr> <tr><td>296403</td><td>WELL</td><td>AL</td><td>03/31/2016</td><td>LO</td><td>045-16000</td><td>697-2C 21</td><td>RI</td></tr> <tr><td>296405</td><td>WELL</td><td>AL</td><td>03/31/2016</td><td>LO</td><td>045-16002</td><td>697-2C 23</td><td>RI</td></tr> <tr><td>296406</td><td>WELL</td><td>AL</td><td>03/31/2016</td><td>LO</td><td>045-16003</td><td>697-2C 25</td><td>RI</td></tr> <tr><td>296425</td><td>WELL</td><td>AL</td><td>03/31/2016</td><td>LO</td><td>045-16021</td><td>697-2C 16</td><td>RI</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	296400	WELL	AL	03/31/2016	LO	045-15997	697-2C 18	RI	296401	WELL	AL	03/31/2016	LO	045-15998	697-2C 14	RI	296402	WELL	AL	03/31/2016	LO	045-15999	697-2C 12	RI	296403	WELL	AL	03/31/2016	LO	045-16000	697-2C 21	RI	296405	WELL	AL	03/31/2016	LO	045-16002	697-2C 23	RI	296406	WELL	AL	03/31/2016	LO	045-16003	697-2C 25	RI	296425	WELL	AL	03/31/2016	LO	045-16021	697-2C 16	RI
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																												
296400	WELL	AL	03/31/2016	LO	045-15997	697-2C 18	RI																																																												
296401	WELL	AL	03/31/2016	LO	045-15998	697-2C 14	RI																																																												
296402	WELL	AL	03/31/2016	LO	045-15999	697-2C 12	RI																																																												
296403	WELL	AL	03/31/2016	LO	045-16000	697-2C 21	RI																																																												
296405	WELL	AL	03/31/2016	LO	045-16002	697-2C 23	RI																																																												
296406	WELL	AL	03/31/2016	LO	045-16003	697-2C 25	RI																																																												
296425	WELL	AL	03/31/2016	LO	045-16021	697-2C 16	RI																																																												

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296400	WELL	AL	03/31/2016	LO	045-15997	697-2C 18	RI
296401	WELL	AL	03/31/2016	LO	045-15998	697-2C 14	RI
296402	WELL	AL	03/31/2016	LO	045-15999	697-2C 12	RI
296403	WELL	AL	03/31/2016	LO	045-16000	697-2C 21	RI
296405	WELL	AL	03/31/2016	LO	045-16002	697-2C 23	RI
296406	WELL	AL	03/31/2016	LO	045-16003	697-2C 25	RI
296425	WELL	AL	03/31/2016	LO	045-16021	697-2C 16	RI

General Comment:

This is an Abandoned Location Inspection, for Seven Wells, listed in Inspected Facilities, above; Permitted for Loc#335985, in Garfield County. APDs First Approved 12/9/2009, Permits Abandoned in 3/31/2013. It does not appear that these AL Wells were drilled on Location with One Producing Well; therefore these would be Well Releases on an Active Location except that there is Evidence of the Wells: Refer to Reclamation Section & Photos attached.

Inspected Facilities

Facility ID: <u>296400</u>	Type: <u>WELL</u>	API Number: <u>045-15997</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296401</u>	Type: <u>WELL</u>	API Number: <u>045-15998</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296402</u>	Type: <u>WELL</u>	API Number: <u>045-15999</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296403</u>	Type: <u>WELL</u>	API Number: <u>045-16000</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296405</u>	Type: <u>WELL</u>	API Number: <u>045-16002</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296406</u>	Type: <u>WELL</u>	API Number: <u>045-16003</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296425</u>	Type: <u>WELL</u>	API Number: <u>045-16021</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: **There is Evidence of the Seven AL Wells. To" ABANDON PERMIT: Permit can only be abandoned if the permitted operation has NOT been conducted. Field inspection will be conducted to verify site status." Gravel filled Cellars are on site in the Positions of the AL Wells. It is not possible to verify if Conductors had been Set. Refer to Photos attached.**

Corrective Action: **Remove all evidence of AL Wells.** Date **01/12/2018**

Overall Final Reclamation

Fail

Well Release on Active Location ☒Multi-Well Location ☒**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401483981	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4324104
680102477	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4324093