

Inspection Photos
Location Name: Sidwell A #26-3
API: 05-123-23561



Photo 1: Location, looking W



Photo 2: Wellhead, looking N



Inspection Photos
Location Name: Sidwell A #26-3
API: 05-123-23561



Photo 3: Weeds in berms and within tank battery



Photo 4: Stained soil in separator house