

Inspection Photos

12/18/2017

Operator: PETRO-CANADA RESOURCES (USA)

INC - 72085

Location ID: 375675

Inspection Doc. Number: 682502972

Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator: PETRO-CANADA RESOURCES (USA) INC - 72085

Location ID: 375675



Photo 1: Photo taken from within the former fenced remediation area, facing west. Photo shows areas appear to have been reseeded and crimped with straw for stabilization. Reclamation in process.



Photo 2: Photo taken from within the former fenced remediation area, facing southwest. Photo shows areas appear to have been reseeded and crimped with straw for stabilization. Reclamation in process.

Inspection Photos

Operator: PETRO-CANADA RESOURCES (USA) INC - 72085

Location ID: 375675



Photo 3: Photo taken from the east end of the former battery facility, facing west. Photo shows areas appear to have been reseeded and crimped with straw for stabilization. Reclamation in process.



Photo 4: Photo taken from the east end of the former battery facility, facing west. Photo shows areas appear to have been reseeded and crimped with straw for stabilization. Reclamation in process, however it is noted that straw mulch does not appear to have been distributed and crimped uniformly.