

# Inspection Photos

12/18/2017

Operator: PWALSH\* FRANK H - 94100

Location ID: 375209

Inspection Doc. Number: 682502980

Adams County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: PWALSH\* FRANK H - 94100  
Location ID: 375209



**Photo 1:** Photo taken from the east end of the former pit location, facing west. Photo shows pit has been recontoured, filled and reclamation appears to have been performed.



**Photo 2:** Photo taken from the east end of the former pit location, facing southwest. Photo shows pit has been recontoured, filled and reclamation appears to have been performed.