

Location Name: Marco Polo

API: 05-043-06228

Inspection Date: 12/15/17




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Marco Polo

API: 05-043-06228

Inspection Date: 12/15/17



Location Name: Marco Polo

API: 05-043-06228

Inspection Date: 12/15/17



Pit



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Marco Polo

API: 05-043-06228

Inspection Date: 12/15/17



Animal tracks inside pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Marco Polo

API: 05-043-06228

Inspection Date: 12/15/17



Netting on east side of pit allows wildlife access



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Marco Polo

API: 05-043-06228

Inspection Date: 12/15/17



Stormwater BMP's on north side of well pad.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources