

Inspection Photos
Location Name: Roth 14-5
API #: 05-123-20586
Location ID: 331375



Wellhead looking east, weeds need to be controlled



Battery looking west

Inspection Photos
Location Name: Roth 14-5
API #: 05-123-20586
Location ID: 331375



Produced water tank does not have NFPA labeling