

**Inspection Photos**  
**Location Name: Bliss 14-3**  
**API #: 05-123-21431**  
**Location ID: 331875**



**Wellhead looking east**



**Stained soil under master valve needs cleaned up**