


Inspection Photos  
Location Name: Hotchkiss 1290 1-34  
Location ID: 324484



**Photo 1. Trash has been removed from around wellhead.**



**Photo 2. Hoses have been removed.**