

Final Reclamation Inspection

December 14, 2017

Operator: CHESAPEAKE OPERATING LLC- 16660

API: 05-123-31630

Weld County, CO

SESW Section 16 T9N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: STATE 16-9-66 #1H
API: 05-123-31630



Google Earth imagery taken October 14, 2017. Photo illustrates the well pad location (~4.3 acres) in relation to adjacent reference areas.

Inspection Photos
Location Name: STATE 16-9-66 #1H
API: 05-123-31630



Photo 1. Photo taken from the entrance of the location, facing North. Approach and gravel pile left behind which has not been reclaimed per Rule 1004 standards.




Photo 2. Photo taken from the western location, facing West. Disturbance area vegetation consists mainly of a crested wheatgrass, another wheatgrass species, wildrye species, and smooth brome- none of these species were observed in the reference area. Reference area vegetation consists mainly of Switchgrass, little bluestem, sideoats grama, and blue grama.

Inspection Photos
Location Name: STATE 16-9-66 #1H
API: 05-123-31630




Photo 3. Photo taken from the western location, facing North. See comments under Photo 2.

Inspection Photos
Location Name: STATE 16-9-66 #1H
API: 05-123-31630



Photo 4. Photo taken from the approximate center of location, facing East. See comments under Photo 2.



Photo 5. Photo taken from the southwest location, facing South. Operator needs to remove excessive rip-rap material that may have been used as stormwater BMPs.