

Inspection Photos
Location Name: McCallum Unit 44
API: 05-057-06019



Photo 1. Overview of location taken at entrance facing west.



Photo 2. Stained soil at wellhead, unmarked riser at wellhead.